

Hambro

AUTOMOTIVE CORPORATION

PARTS AND SERVICE BULLETIN

• 734 GRAND AVENUE • RIDGEFIELD, N. J. • WH



June 22, 1960

TO ALL DISTRIEUTORS AND DEALERS

Re: Austin Healey 100-6  
Austin Healey 3000  
Equipped with Overdrive  
Possible damage to wiring harness

Gentlemen:

Whenever the above mentioned vehicles are brought in for service, pre-delivery inspection, after-sales service, or routine checks, the position of the capillary tube from the temperature gauge element to the dial indicator should be carefully checked to ensure that it cannot possibly contact the terminals of the overdrive throttle switch located on the firewall.

Failure to check this point may result in burning of the wiring harness.

It is particularly important that this operation should be checked after the valve rocker cover has been removed for any reason.

Very truly yours,

HAMBRO AUTOMOTIVE CORPORATION

A.D. Woods  
Service Manager (Technical)

ADW/rw/t