AUSTIN SERVICE JOURNAL

Distributor & Dealer Organization
No. A / 295

Fleet Users
No.

18 October 1960

## IMPORTANT MODIFICATIONS

| | | Parts List Amendment No. |
|---|---|---|
| Radiator hoses | From Car No. 12049 (BN.7) ) 12063 (BT.7) ) Healey 3000<br>To prevent collapse<br>Hoses with thicker walls introduced.<br>Interchangeable. | PAU / 1096 1099 |
| Cylinder block side covers | From Engine No. 15AMW-N-H.43192 ) 15AMW-N-L.42701 ) 15AMW-U-H.46351 ) 15AMW-U-H.45019 ) A.55 Cambridge (Mark II)<br>To reduce possibility of oil leaks<br>Stiffness of side covers increased by slight thickening of material.<br>Interchangeable. | PAU / 1124 |
| Change-speed lever | From Engine No. 20598 - Healey 3000<br>To improve gear-change operation<br>Change-speed lever now cranked at knob end.<br>Interchangeable. | PAU / 1130 |

LITHOGRAPHED IN ENGLAND