



Distributor & Dealer  
Organization

No. A / 275

Fleet Users

No. ....

9 September 1960

## SQUEAL FROM DISC BRAKES

## AUSTIN-HEALEY 3000

This may be prevented by fitting four anti-squeal shims, Part No. BHA4195, which should be positioned between each of the brake pads and pistons, with the arrow mark pointing in direction of forward rotation of wheel, as shown at 'A'.

