

# AUSTIN SERVICE JOURNAL

Distributor & Dealer  
Organization

No. A / 289

Fleet Users

No. ....

18 October 1960

REAR TYRE FOULING

AUSTIN-HEALEY 3000

At Car Nos. 10309 (BN.7) and 10299 (BT.7) the RS.4 Road Speed tyres were replaced by RS.5 tyres having an improved tread pattern. The new tyres may be fitted in sets to earlier cars.

However, when fitting RS.5 tyres to cars prior to those quoted above, it is essential that the bolts securing the bump-rubber bracket to the wheel arch are shortened by 0.5" (12.7 mm.).

