



# AUSTIN SERVICE JOURNAL

Distributor & Dealer  
Organization

No. / 310

Fleet Users

No. ....

22 November 1960

REPLACEMENT SHELL &  
UNDERFRAME ASSEMBLY -  
ADDITIONAL PARTS REQUIRED

AUSTIN-HEALEY Sprite

When supplying a body shell & underframe assy. AHA5145, for cars prior to 5477 (except 5137, 5287, 5288), supply also:

	<u>Part No.</u>
1 Exhaust pipe	AHA5360
1 Bracket - exhaust	AHA5361
2 Clips - rear spring	AHA5221
4 Bolts - spring to frame	HBZO626

and the following additional items for cars prior to 4333 and for cars 4471, 4622, 4680, 4684:

	<u>Part No.</u>
2 Shock absorber links	AHA5446
1 Mounting bracket (shock absorber) R/H	AHA5305
1 Mounting bracket (shock absorber) L/H	AHA5306
2 Bolts - shock absorber to bracket	HBZO630
2 Bolts - shock absorber to bracket	HBZO612
4 Nuts	LNZ106
4 Plain washers	PWZ106
4 Spring washers	LWZ306
1 Wheel arch liner R/H )	) for Part Nos. refer to Service Parts List.
1 Wheel arch liner L/H )	
1 Heelboard liner assy. )	