



**hambro**  
AUTOMOTIVE CORPORATION

**PARTS AND SERVICE BULLETIN**

• 2227-29 WEBSTER AVENUE • BRONX 57, N. Y. • CY 8-4500

September 16, 1957

T O A L L D I S T R I B U T O R S A N D D E A L E R S

Re: Austin Healey Body Trim

We have received several complaints regarding the trim of the 1957 Austin Healey 100-Six.

The following method of rectification is recommended:-

Clean all loose material with Naphtha gas and then re-gluue with "3M" (Minnesota Mining and Manufacturing) product adhesive No. E.C. 1022.

A reasonable allowance for labor will be made on submission of a regular warranty claim through the usual channels.

Yours very truly,  
HAMBRO AUTOMOTIVE CORPORATION

A handwritten signature in cursive script that reads "G.O. Ehrman".

G.O. Ehrman  
Service Executive

GOE:br