



# Hambro

AUTOMOTIVE CORPORATION

## PARTS AND SERVICE BULLETIN

• 734 GRAND AVENUE • RIDGEFIELD, N. J. • WH 3-0222

May 19, 1960

TO ALL DISTRIBUTORS AND DEALERSRE: DISC BRAKES AUSTIN  
HEALEY 3000

We have had a number of inquiries with regard to scoring of discs on the front brakes as fitted to the Austin Healey 3000 vehicles.

Scoring of brake discs is not detrimental providing that the scoring is concentric, even and not excessive. However, if it is thought advisable, the disc faces may be ground to a maximum of .040" off.

The following points must be observed:

- a) No more than .040" is to be removed per disc, that is after grinding the disc thickness must not be less than .340/.335, the original thickness of the disc being .380/.375.
- b) The faces must run true to within .002".
- c) The thickness must be parallel to within .001".

The above-mentioned figures must be adhered to for satisfactory braking on this vehicle.

Yours very truly,  
HAMBRO AUTOMOTIVE CORP.

*A. D. Woods*  
A. D. Woods,  
Service Manager (Technical)

ADW:lhf