



# TECHNICAL SERVICE BULLETIN

The British Motor Corporation / Hambro Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

September 29, 1967

TO ALL DISTRIBUTORS AND DEALERS

Re: Cooling System

Mini Range  
1100 Range  
Austin Healey Sprite  
Austin Healey 3000  
Morris Minor 1000  
MG Midget  
MGB

Where thermostats are removed, as is customary in hot climates, it is essential to fit a thermostat blanking sleeve, Part No. 11G 176. If this is omitted, the resultant inefficient coolant flow and higher running temperatures may possibly lead to an engine seizure.

MG • AUSTIN HEALEY • MORRIS • AUSTIN • SPRITE • MIDGET