

Distributor & Dealer
Organization

No. A / 285

Fleet Users

No.

30 Sept. 1960

IMPORTANT MODIFICATIONS

Parts List
Amendment No.

Shock absorbers - front	<u>From Car No. 108180 - RHD</u>) <u>A.40</u>	
	<u>108089 - LHD</u>) <u>Series A2S.6</u>	PAU/1065
	<u>104920 - RHD</u>) <u>A.40 COUNTRYMAN</u>	
	<u>104834 - LHD</u>) <u>Series AAW.6</u>	PAU/1038
- rear	<u>From Car No. 111682 - RHD</u>) <u>A.40</u>	
	<u>107362 - LHD</u>) <u>Series A2S.6</u>	PAU/1057
	<u>111729 - RHD</u>) <u>A.40 COUNTRYMAN</u>	
	<u>111811 - LHD</u>) <u>Series AAW.6</u>	PAU/1060

To provide softer ride.

Shock absorber settings modified.

Interchangeable.

Carburettors	<u>From Engine No. 18656 - AUSTIN-HEALEY 3000</u>	PAU/1096
--------------	---	----------

Improved design.

Introduction of modified 'fast idle' actuating mechanism incorporating roller type cam shoe and rod assembly.

Jet housing modified to suit.

Carburettors interchangeable in pairs.

Overdrive gearbox - oil strainer & drain plug	<u>From Engine No. 8745 - AUSTIN-HEALEY 3000</u>	PAU/1097
---	--	----------

Improved design.

Oil drain plug for front casing and oil strainer modified to suit magnet fitted in drain plug.

Interchangeable.

Driving mirror	<u>From Body No. 87932 - A.55 CAMBRIDGE (Mark II)</u>	PAU/1093
----------------	---	----------

To eliminate vibration

Stouter bracket introduced and mirror modified to suit.

Interchangeable.