



Distributor & Dealer  
Organization

No. A / 306

Fleet Users

No. ....


11 Nov. 1960

## SUMP PROTECTION PLATE

AUSTIN-HEALEY 3000

(BN. 7; BT. 7)

To prevent sump damage in very rough country, a mild steel protection plate (Fig. 1) may be welded to the sump in six places (Fig. 2)



Sumps should be drained and removed before welding. Arc-welding is preferable if distortion is to be avoided and Sifbronze will also enable a satisfactory job to be made.